

# **Fabric Report**

**David Flatman**

Replacement windows fitted at the back of church (Feb 2018)

Replacement rear door and associated windows (Feb 2018)

Lower Hall walls painted and curtains cleaned

Two sets of round table racks made and fitted in back corridor.

Replacement of Kitchen water heater

The normal yearly procedures for fire alarm testing and emergency lighting, fire equipment and gas safety checks were carried out. Two replacement fire extinguishers were required and fitted.